

POLITEKNIK KESEHATAN TANJUNGPINANG
JURUSAN KESEHATAN LINGKUNGAN
Laporan Tugas Akhir
Deaz Maharani (203451051)

Gambaran Pelaksanaan Kesehatan dan Keselamatan Kerja (K3) Pada Bagian Produksi di PERUMDA Air Minum Way Rilau Kota Bandar Lampung Tahun 2023, xiv + 68 Halaman + 9 Tabel + 8 Gambar + 5 Lampiran

ABSTRAK

Kecelakaan kerja yang terjadi di Indonesia menunjukkan angka - angka yang harus diberikan perhatian serius untuk pekerja Indonesia. Keselamatan tenaga kerja dalam melakukan pekerjaan telah mendapatkan perhatian dari pemerintah ataupun dari perusahaan. Tujuan penelitian ini adalah ingin mengetahui struktur organisasi K3, Proses Produksi dan Faktor Kecelakaan Kerja, Ketersediaan dan Penggunaan Alat Pelindung Diri serta Ketersediaan tentang Rambu – Rambu K3 di PERUMDA Air Minum Way Rilau Kota Bandar Lampung Tahun 2023.

Dari penelitian yang telah dilakukan diperoleh hasil sudah ada struktur organisasi K3, proses produksi yang dilakukan pekerja sudah baik, kurangnya ketersediaan Alat Pelindung Diri yang tidak sesuai dengan jenis bahaya dan kebutuhan / kenyamanan pekerja, dan tidak tersedianya rambu – rambu K3 yang seharusnya terpasang di sekeliling tempat kerja untuk mengetahui resiko kecelakaan yang ada di tempat tersebut.

Oleh karena itu, perusahaan harus meningkatkan struktur organisasi K3 dengan membentuk Panitia Pembina Kesehatan Dan Keselamatan Kerja, tetap meningkatkan proses produksi yang baik untuk kepuasan konsumen, serta menyediakan alat pelindung diri yang sesuai dengan kebutuhan para pekerja dan memperhatikan untuk pembaharuan Alat Pelindung Diri demi kenyamanan para pekerja dan memasang Rambu – Rambu K3 untuk mengurangi resiko kecelakaan kerja.

Kata kunci : Kesehatan Keselamatan Kerja, APD, Rambu-Rambu K3

Daftar bacaan : (1970 – 2022)

POLYTECHNIC OF HEALTH TANJUNGKARANG
DEPARTEMENT OF ENVIRONMENTAL HEALTH
Final Project Report
Deaz Maharani (2013451051)

Description of Occupational Health and Safety (K3) Implementation in the Production Section at PERUMDA Air Minum Way Rilau Bandar Lampung City in 2023, xiv + 68 pages + 9 tables + 8 pictures + 5 attachments

ABSTRACT

Work accidents that have occurred in Indonesia show figures that must be given serious attention to Indonesian workers. Labor safety in carrying out work has received attention from the government or from companies. The purpose of this study was to find out the OHS organizational structure, Production Process and Work Accident Factors, Availability and Use of Personal Protective Equipment and Availability of K3 Signs at PERUMDA Air Minum Way Rilau Bandar Lampung City in 2023.

From the research that has been carried out, the results show that the organizational structure is quite good, the production process carried out by workers is good, the lack of availability of Personal Protective Equipment that is not in accordance with the type of hazard and the needs / comfort of workers, and the unavailability of K3 signs that should be installed around workplace to find out the risk of accidents that exist in that place.

Therefore, companies must improve the OHS organizational structure by forming an Occupational Health and Safety Advisory Committee, continue to improve production processes that are good for consumer satisfaction, and provide personal protective equipment that suits the needs of workers and pay attention to updating Personal Protective Equipment for the comfort of employees. workers and install K3 Signs to reduce the risk of work accidents.

Keywords : Occupational health safety, personal protective equipment, K3 signs
Reading List : (1970 – 2022)