

**POLITEKNIK KEMENTERIAN KESEHATAN TANJUNG KARANG**

**JURUSAN KESEHATAN LINGKUNGAN**

Tugas Akhir, 04 Juli 2023

Aldi Kurniawan

**GAMBARAN SANITASI SEKOLAH MENENGAH ATAS KECAMATAN TULANG  
BAWANG UDIK TAHUN 2023**

± 57 Halaman, 11 Tabel, 2 Gambar, 8 Lampiran

**RINGKASAN**

Sekolah adalah suatu lembaga yang mempunyai peran strategis terutama mendidik dan menyiapkan sumber daya manusia. Fungsi Sekolah sebagai sarana pembelajaran dan pendidikan juga berperan dalam hubungan dengan sanitasi sekolah, jika fasilitas sanitasi tidak memadai maka akan mempengaruhi status kesehatan siswa.

Jenis penelitian ini adalah penelitian deskriptif yaitu suatu penelitian yang dilakukan dengan tujuan utama untuk membuat gambaran/deskriptif tentang suatu keadaan secara objektif.

Berdasarkan hasil inspeksi sanitasi lokasi dan lingkungan sekolah menunjukkan untuk lingkungan halaman sekolah 50% tidak memenuhi syarat di SMA 01 Tulang Bawang Udik karena halaman sekolah yang kurang bersih dan rapi, hasil inspeksi sanitasi bagian dalam bangunan sekolah menunjukkan untuk ventilasi sekolah 50% tidak memenuhi syarat di SMA 01 Tulang Bawang Udik karena karna ventilasi tertutup pada setiap ruangan, hasil inspeksi sanitasi air bersih sekolah menunjukkan untuk Air bersih tersedia 15 liter/orang/hari sekolah 50% tidak memenuhi syarat di SMA 01 Tulang Bawang Udik karena tidak adanya tower di sekolah tersebut, hasil inspeksi toilet sekolah menunjukkan untuk jumlah toilet sekolah 0% tidak memenuhi syarat untuk kedua sekolah di tulang bawang udik karena jumlah toilet dengan mahasiswa tidak mencakupi, hasil inspeksi sanitasi toilet sekolah menunjukkan untuk spal tidak mecemari lingkungan 100% sisanya tidak memenuhi syarat untuk kedua sekolah tersebut, karna sejauh ini belum ada keluhan dari warga sekitar akan hal tersebut, hasil inspeksi sanitasi tempat sampah sekolah untuk Jarak TPS 50% tidak memenuhi syarat di SMA 01 Tulang Bawang Udik karena jarak sampah antar ruang kurang dari 10 meter.

Berdasarkan hasil inspeksi sanitasi yang dilakukan pada 2 sekolah yang ada di Kecamatan Tulang Bawang Udik maka dapat disimpulkan 2 sekolah sudah memenuhi persyaratan untuk lingkungan halaman sekolah, bagian dalam ruangan, air bersih dan toilet dan tidak memenuhi syarat untuk SPAL di 2 sekolah di kecamatan tulang bawang udik.

Kata Kunci : Gambaran Sanitasi Sekolah Menengah Atas

Daftar Bacaan : 11 (2003-2023)

**TANJUNG KARANG MINISTRY OF HEALTH POLYTECHNIC**

**DEPARTMENT OF ENVIRONMENTAL HEALTH**

**Final Project, 2023**

Aldi Kurniawan

## **DESCRIPTION OF HIGH SCHOOL SANITATION IN TULANG BANG UDIK SUB-DISTRICT, 2023**

± 57 pages, 11 tables, 2 pictures, 8 attachments

### **ABSTRACT**

School is an institution that has a strategic role, especially educating and preparing human resources. The function of the school as a learning and educational facility also plays a role in relation to school sanitation, if sanitation facilities are inadequate it will affect the health status of students.

This type of research is descriptive research, namely a research conducted with the main objective to make a description/descriptive about a situation objectively.

Based on the results of sanitation inspections of the school location and environment, it showed that for the school yard environment 50% did not meet the requirements at SMA 01 Tulang Bawang Udik because the school yard was not clean and tidy, the results of a sanitary inspection of the inside of the school building showed that 50% of school ventilation did not meet the requirements in SMA 01 Tulang Bawang Udik because due to closed ventilation in every room, the results of a school clean water sanitation inspection showed that clean water available 15 liters/person/school day 50% did not meet the requirements at SMA 01 Tulang Bawang Udik because there was no tower at the school. the results of the inspection of school toilets show that for the number of school toilets 0% does not meet the requirements for the two schools in Tulang Bawang village because the number of toilets with students does not cover them, the results of the sanitary inspection of school toilets show that the spas do not pollute the environment 100% the rest do not meet the requirements for the two schools , because so far there have been no complaints from local residents about this, the results of a sanitation inspection of the school trash for a 50% TPS distance do not meet the requirements at SMA 01 Tulang Bawang Udik because the distance between the trash cans is less than 10 meters.

Based on the results of sanitation inspections conducted at 2 schools in the Tulang Bawang Udik District, it can be concluded that 2 schools met the requirements for the school yard environment, indoor areas, clean water and toilets and did not meet the requirements for SPAL in 2 schools in the Tulang Bawang district. hick.

Keywords: Description of High School Sanitation

Reading List : 11 (2003-2023)