

**POLITEKNIK KESEHATAN KEMENKES TANJUNG
KARANG JURUSAN KESEHATAN LINGKUNGAN
Laporan Tugas Akhir, Mei 2023**

Rifal Dientama

**Gambaran Fasilitas Sanitasi Dasar Di Sekolah Dasar Kecamatan Batu
Brak Kabupaten Lampung Barat Tahun 2023**

Xvii + 55 halaman, 2 gambar, 9 tabel dan 6 lampiran.

RINGKASAN

Sanitasi dasar sekolah adalah syarat kesehatan lingkungan yang harus dipunyai oleh setiap sekolah untuk memenuhi kebutuhan siswa dan siswi..

Tujuan dalam penelitian ini untuk mengetahui Gambaran Fasilitas Sanitasi Dasar di Sekolah Dasar. Jenis penelitian ini merupakan penelitian deskriptif yaitu menggambarkan keadaan Fasilitas Sanitasi Dasar di Sekolah Dasar Kecamatan Batu Brak Kabupaten Lampung Barat Tahun 2023

Hasil penelitian dari 11 Sekolah Dasar Batu Brak Kondisi sarana penyediaan air bersih, kondisi sarana pembuangan tinja/jamban toilet yang sudah dipisah antara laki laki dan perempuan (100%), toilet tidak dalam keadaan bersih (90,90), sarana pembuangan air limbah tidak terpisahnya pembuangan air limbah dengan saluran penuntasan air hujan (100%), pembuangan air limbah yang tidak tertutup (100%), SPAL yang mencemari lingkungan (63,63%), air limbah tidak dibuang melalui tanki septic dan kemudian diresapkan ke dalam tanah (100%). sarana pembuangan sampah belum tersedianya sampah di setiap kelas (18,18%), tempat sampah masih banyak yang terbuka (36,36%)

Kesimpulan dari penelitian ini masih banyak kondisi sekolah yang tidak memperhatikan kondisi fasilitas sanitasi dasar sekolah. Diharapkan dari hasil penelitian ini sekolah dan institusi yang berkaitan dengan sekolah untuk membantu memperbaiki kondisi sarana yang kurang baik.

Kata Kunci: Penyediaan air bersih,,SPAL,P sampah
Daftar Bacaan : 13 (2002-2022)

**POLYTECHNIC OF HEALTH MINISTRY OF HEALTH TANJUNG
KARANG DEPARTMENT OF ENVIRONMENTAL HEALTH
Final Project Report, May 2023**

Rifal Dientama

**Overview of Basic Sanitation Facilities at Elementary Schools in Batu Brak
District, West Lampung Regency in 2023**

xvii + 55 pages, 2 pictures, 9 tables and 6 attachments

ABSTRACT

Basic school sanitation is an environmental health requirement that must be owned by every school to meet the needs of students. The purpose of this study was to find out the description of basic sanitation facilities in elementary schools in Batu Brak sub-district, West Lampung regency in 2023. This type of research is a descriptive study, which describes the condition of basic sanitation facilities in elementary schools in Batu Brak sub-district, West Lampung district in 2023.

Based on the research that has been done, the results include: Condition of clean water supply facilities in Elementary Schools, Batu Brak District, West Lampung Regency, out of 11 schools that have Stool disposal facilities/toilet latrines that have been separated between boys and girls (100%), toilets not in a clean condition (90.90) The condition of the waste water disposal facilities is that the waste water disposal is not separated from the rainwater finishing channel (100%), the waste water disposal is not closed (100%), the SPAL pollutes the environment (63.63%), the waste water is not disposed of through a septic tank and then impregnated into the soil (100%). The condition of waste disposal facilities is that there is no available waste in each class (18.18%), there are still many open trash cans (36.36

The conclusion from this study is that there are still many school conditions that do not pay attention to the condition of the school's basic sanitation facilities. It is hoped that from the results of this study schools and institutions related to schools will help improve the condition of facilities that are not good.

Keywords: Provision of clean water, SPAL, P garbage
Reading List : 13 (2002-2022)