

POLITEKNIK KESEHATAN KEMENKES TANJUNGKARANG
JURUSAN KESEHATAN LINGKUNGAN
PROGRAM STUDI DIPLOMA TIGA

Laporan Tugas Akhir, Mei 2024

Aisyah Putri Adinda

“Gambaran Fasilitas Sanitasi Masjid di Kelurahan Rajabasa Raya Kecamatan Rajabasa Kota Bandar Lampung Tahun 2024”

Ringkasan

Kondisi sanitasi masjid dapat dilihat dari kondisi umum, kondisi bagian dalam dan kondisi fasilitas sanitasi masjid. Pada masjid di Kelurahan Rajabasa Raya Kecamatan Rajabasa Kota Bandar Lampung masih ditemukan masalah sanitasi seperti kondisi lingkungan yang tidak bersih, sampah berserakan di halaman masjid, tempat sampah tidak tersedia dengan jumlah yang cukup dan jamban masih kurang ada yang kurang bersih. Tujuan penelitian ini adalah untuk mengetahui Gambaran Fasilitas Sanitasi Masjid di Kelurahan Rajabasa Raya Kecamatan Rajabasa Kota Bandar Lampung.

Penelitian ini yaitu seluruh masjid yang ada di Kelurahan Rajabasa Raya Kecamatan Rajabasa Kota Bandar Lampung yang berjumlah 8 Masjid. Penelitian ini bersifat deskriptif, yang menggambarkan Kondisi Fasilitas Sanitasi Masjid di Kelurahan Rajabasa Raya Kecamatan Rajabasa Kota Bandar Lampung. Penelitian dilakukan pada bulan Maret - Mei 2024. Data diperoleh melalui observasi lapangan menggunakan form Inspeksi Sanitasi Masjid kemudian di analisis dan disajikan dalam bentuk tabel dan narasi.

Berdasarkan hasil penelitian yang dilakukan di Kelurahan Rajabasa Raya Kecamatan Rajabasa Kota Bandar Lampung. Maka dapat disimpulkan bahwa kondisi Umum Masjid memenuhi syarat dengan persentase 70%, kondisi bagian dalam masjid memenuhi syarat dengan persentase 70% dan kondisi fasilitas sanitasi Masjid memenuhi syarat dengan persentase 70%.

Disarankan kepada Marbot masjid untuk menjaga kebersihan lingkungan masjid dengan menyediakan tempat sampah minimal 4 buah dengan penempatan masing-masing berjarak 10 m agar sampah yang ada di masjid dapat tertampung semuanya sehingga tidak ada yang berserakan dan juga disarankan kepada pengunjung agar tidak membuang sampah sembarangan serta memperbaiki system drainase.

Kata Kunci: Sanitasi Masjid, Kelurahan Rajabasa Raya, Kecamatan Rajabasa
Daftar kunci: 15 (2003-2023)

POLYTECHNIC OF HEALTH MINISTRY OF HEALTH TANJUNGKARANG
DEPARTMENT OF ENVIRONMENTAL HEALTH
PROGRAM FOR DIPLOMA THREE OF ENVIRONMENTAL SANITATION,

Final Project Repost, Mei 2024

Aisyah Putri Adinda

"Overview of Mosque Sanitation Facilities in Rajabasa Raya Village, Rajabasa District, Bandar Lampung City in 2024"

Abstract

The sanitary condition of the mosque can be seen from the general condition, the internal condition and the condition of the mosque sanitation facility. In the mosque in Rajabasa Raya Village, Rajabasa District, Bandar Lampung City, sanitation problems are still found such as unclean environmental conditions, garbage scattered in the mosque yard, garbage cans are not available in sufficient quantities and latrines are still lacking, some are not clean. The purpose of this study is to find out the Overview of Mosque Sanitation Rajabasa Raya Village, Rajabasa District, Bandar Lampung City

This research is all mosques in Rajabasa Raya Village, Rajabasa District, Bandar Lampung City, totaling 8 mosques. This research is descriptive, describing the condition of mosque sanitation facilities in Rajabasa Raya Village, Rajabasa District, Bandar Lampung City. The research was conducted in March - May 2024. Data was obtained through field observation using the Mosque Sanitation Inspection form then analyzed and presented in the form of tables and narratives.

Based on the results of research conducted in Rajabasa Raya Village, Rajabasa District, Bandar Lampung City. Therefore, it can be concluded that the general condition of the mosque meets the requirements with a percentage of 70%, the condition of the inside of the mosque meets the requirements with a percentage of 70% and the condition of the mosque sanitation facilities meets the requirements with a percentage of 70%.

It is recommended to the mosque Marbot to maintain the cleanliness of the mosque environment by providing a minimum of 4 garbage cans with a placement of 10 m each so that the garbage in the mosque can be accommodated so that nothing is scattered and it is also recommended to visitors not to throw garbage carelessly and improve the drainage system.

Keywords: *Sanitasi Masjid, Kelurahan Rajabasa Raya, Kecamatan Rajabasa*

Bibliography: *15 (2003-2023)*