

POLITEKNIK KESEHATAN TANJUNG KARANG
JURUSAN KESEHATAN LINGKUNGAN
Laporan Tugas Akhir, 2025

Anggun Dafita Sekar Arum (2213451113)

Kondisi Sanitasi Di Pasar Tradisional Tanggulangin Kecamatan Punggur
Kabupaten Lampung Tengah Tahun 2025

xvii + 83 halaman, 7 tabel, 2 gambar, dan 6 lampiran.

RINGKASAN

Pasar tradisional di Indonesia masih menghadapi berbagai permasalahan serius, terutama terkait kondisi fisik bangunan dan aspek kebersihan pasar yang belum optimal. Lingkungan dengan sanitasi yang tidak memadai dapat memberikan dampak negatif terhadap masyarakat yang beraktivitas didalamnya. Oleh karena itu, diperlukan pengawasan terhadap sanitasi dan kesehatan lingkungan. Tujuan utama dari pengawasan serta pengendalian sanitasi lingkungan adalah untuk mencegah terjadinya penularan penyakit dan kecelakaan, dengan cara melindungi manusia dan lingkungan sekitarnya. Berdasarkan hasil observasi awal, ditemukan bahwa kondisi pasar bau, tidak tersedia fasilitas cuci tangan, tempat sampah di setiap kios hanya berupa keranjang terbuka yang tidak kedap air, banyaknya tumpukan sampah yang berserakan serta saluran limbah tidak lancar. Penelitian ini bertujuan untuk mengetahui kondisi sanitasi di lingkungan Pasar Tradisional Tanggulangin.

Penelitian ini menggunakan pendekatan deskriptif melalui metode observasi dan wawancara guna mengidentifikasi kondisi sanitasi lingkungan di Pasar Tanggulangin. Fokus penelitian ini meliputi penyediaan air bersih, kamar mandi dan toilet, pengelolaan sampah, sistem drainase, tempat cuci tangan serta pengendalian vektor dan binatang pembawa penyakit.

Hasil yang diperoleh menunjukkan bahwa ketersediaan air bersih di Pasar Tanggulangin belum memenuhi kebutuhan secara kuantitas. Selain itu, belum tersedia tempat cuci tangan dengan sabun, tempat sampah tertutup, dan sistem ventilasi yang memadai. Tempat Pembuangan Sementara berada di jalur utama pasar dan berdekatan dengan aktivitas pedagang, yang menyebabkan gangguan kenyamanan bagi pedagang maupun pengunjung. Sistem drainase juga belum dilengkapi dengan penutup kisi-kisi logam serta aliran drainase tidak lancar akibat masih banyak sampah yang menumpuk di saluran tersebut.

Kata Kunci : Sanitasi, Pasar, Kesehatan

Daftar Bacaan : 14 (2012 - 2024)

HEALTH POLYTECHNIC OF TANJUNG KARANG
ENVIRONMENTAL HEALTH DEPARTMENT

Anggun Dafita Sekar Arum (2213451113)

Sanitation Conditions in Tanggulangin Traditional Market, Punggur District,
Central Lampung Regency in 2025

xvii + 83 pages, 7 tables, 2 figures, and 6 attachments.

ABSTRACT

Traditional markets in Indonesia still face various serious problems, especially related to the physical condition of the building and the market's hygiene aspects which are not yet optimal. An environment with inadequate sanitation can have a negative impact on the community who are active in it. Therefore, supervision of environmental sanitation and health is needed. The main purpose of environmental sanitation supervision and control is to prevent the transmission of disease and accidents, by protecting humans and the surrounding environment. Based on the results of initial observations, it was found that the market conditions were smelly, there were no hand washing facilities, the trash bins in each stall were only open baskets that were not waterproof, there were many piles of scattered garbage and the waste channels were not smooth. This study aims to determine the sanitation conditions in the Tanggulangin Traditional Market environment.

This study uses a descriptive approach through observation and interview methods to identify environmental sanitation conditions in Tanggulangin Market. The focus of this study includes the provision of clean water, bathrooms and toilets, waste management, drainage systems, hand washing facilities and control of vectors and disease-carrying animals.

The results obtained indicate that the availability of clean water in Tanggulangin Market has not met the needs in terms of quantity. In addition, there are no hand washing facilities with soap, closed trash bins, and adequate ventilation systems. The Temporary Disposal Site is located on the main market route and is close to trader activities, which causes discomfort for traders and visitors. The drainage system is also not equipped with metal grid covers and the drainage flow is not smooth because there is still a lot of garbage piled up in the channel.

Keywords : Sanitation, Market, Health

Reading List : 14 (2012 - 2024)