

**POLITEKNIK KESEHATAN TANJUNG KARANG
JURUSAN KESEHATAN LINGKUNGAN**

Tugas Akhir, Juni 2021

Yoel Julianto

**GAMBARAN SANITASI DASAR GEREJA DI DESA NGESTIKARYA
KECAMATAN WAWAY KARYA LAMPUNG TIMUR
TAHUN 2021**

XV+42 Halaman 2 Gambar, 5 Tabel

RINGKASAN

Sanitasi tempat-tempat umum adalah suatu usaha pencegahan penyakit yang menitik beratkan kegiatannya pada usaha-usaha kebersihan / kesehatan tempat-tempat umum (TTU) dalam melayani masyarakat umum sehubungan dengan aktivitas tempat-tempat umum tersebut secara fisiologis, psikologis, mencegah terjadinya penularan penyakit atau kecelakaan serta estetika, antar penghuni, pengguna, dan masyarakat sekitarnya.

Gereja adalah salah satu tempat ibadah umat Nasrani. Menurut data dari Kementerian Agama Provinsi Lampung Tahun 2018 jumlah umat Kristiani yang ada di Lampung Timur adalah 12.460 umat dari 114 Gereja Kristen sedangkan untuk umat Katolik jumlahnya ada 13.482 umat dari 29 Gereja Katolik yang menyebar diseluruh wilayah Lampung Timur.

Dari hasil pengamatan yang telah dilakukan terhadap 2 Gereja (Gereja Santo Yohanes dan Gereja GBI Wonoroto) yang berada di Desa Ngestikarya diperoleh hasil bahwa keduanya belum memenuhi syarat dari lima aspek sanitasi yang diamati, aspek yang menunjukkan masalah adalah saluran pembuangan air limbah (SPAL) yang tidak memenuhi syarat dikarenakan konstruksi dari SPAL Gereja yang tidak tertutup dan tidak kedap dengan air.

Permasalahan tertinggi pada Gereja yaitu sarana tempat pembuangan sampah dari 2 Gereja tersebut tidak memenuhi syarat, dikarenakan konstruksinya yang dimana tidak memiliki tutup dan tidak kedap air.

Dari 2 Gereja (Gereja Santo Yohanes dan Gereja GBI Wonoroto) tersebut sarana penyediaan air bersih (SAB) pada Gereja di Desa Ngestikarya memenuhi syarat secara fisik, kualitas jamban pada Gereja di Desa Ngestikarya juga masih ada yang kurang, ada 1 Gereja yang toilet nya 1 untuk laki-laki dan perempuan, sehingga dapat menyebabkan antrian.

Kata Kunci	: Sanitasi tempat-tempat umum (STTU), lingkungan dan bangunan, kualitas penyediaan air bersih, SPAL, kondisi Jamban, kondisi pembuangan sampah.
Daftar Bacaan	: 9

HEALTH POLYTECHNIC, KEMENKES TANJUNG KARANG DEPARTMENT OF ENVIRONMENTAL HEALTH

Final Project, June 2021

Yoel Julianto

DESCRIPTION OF BASIC SANITATION OF THE CHURCH IN NGESTIKARYA VILLAGE, WAWAY KARYA DISTRICT, LAMPUNG TIMUR YEAR 2021

XV+42 Page 2 Pictures, 5 Tables

ABSTRACT

Sanitation of public places is an effort to prevent disease which focuses its activities on cleaning/health efforts of public places (TTU) in serving the general public in connection with the activities of these public places physiologically, psychologically, preventing the occurrence of disease transmission or accidents as well as aesthetics. , between residents, users, and the surrounding community.

The church is a place of worship for Christians. According to data from the Ministry of Religion of Lampung Province in 2018, the number of Christians in East Lampung is 12,460 people from 114 Christian churches, while for Catholics there are 13,482 people from 29 Catholic Churches spread throughout the East Lampung region.

From the results of observations that have been carried out on 2 churches in Ngestikarya Village, the results show that both of them do not meet the requirements of the five sanitation aspects observed, the aspect that shows the problem is the waste water sewer (SPAL) which does not meet the requirements because the construction of the church's SPAL is not closed and not impermeable to water.

The highest problem with the church is that the waste disposal facilities from the 2 churches do not meet the requirements because the construction does not have a lid and is not watertight.

Of the 2 churches, the clean water supply facility (SAB) at the church in Ngestikarya Village meets the physical requirements the quality of the latrines at the church in Ngestikarya Village is also still lacking, there is 1 church with 1 toilet for men and women, so it can cause queues.

Keywords : Sanitation of public places (STTU), the environment and buildings, quality of clean water supply, SPAL, condition Latrine, garbage disposal conditions

Reading list : 9